



# HEAVY DUTY DRILL TYPE NW10

Rath Wolf

- WASHER(3 OFF) 231.1.19
- SCREW(2 OFF) 602.1.25
- SCREW(4 OFF) 602.1.23
- STUD(4 OFF) 229.1.04
- NUT(4 OFF) 604.1.23
- WASHER(4 OFF) 231.1.19
- HANDLE 329.1.23

- COVER 278.1.74
- SCREW (3 OFF) 600.1.08
- SCREW (4 OFF) 801.1.28
- WASHER(4 OFF) 606.1.07

- INSULATION STAIP(2 OFF) 600.1.40
- BRUSH HOLDER BLOCK (2 OFF) 600.1.23
- BRUSH HOLDER(2 OFF) 252.1.25
- CARBON BRUSH (2 OFF) 251.1.29

- ARMATURE ASSEMBLY 822.3.21

- FLED ASSEMBLY 821.3.13

- FLANGE 409.1.15
- SCREW(2 OFF) 600.1.04

- WASHER(2 OFF) 231.1.17

- BEARING 272.1.43

- GREASE NIPPLE(2 OFF) 800.1.30
- GEAR PLATE 270.1.32

- NUT 604.1.40
- KEY 275.1.79
- GEAR 300.1.65
- BEARING 272.1.65
- WASHER 606.1.03
- WASHER 235.1.24
- SHIM 322.1.25
- WASHER 226.1.14
- CIRCLIP 311.1.26
- SPINDLE 290.1.78

- SHIM 322.1.27
- WASHER 235.1.22
- BEARING 272.1.54
- BEARING 272.1.49

- RIVET(2 OFF) 226.1.02

- 360.1.52 NAME PLATE
- 358.1.54 NAME PLATE

- 600.1.07 (2 OFF) SCREW

- 272.1.23 BEARING

- 278.1.62 COVER

- INNER GEAR PLATE END

- GEAR BOX END

- 235.1.23 WASHER
- 322.1.28 SHIM
- 312.1.14 BEARING COVER
- 311.1.34 CIRCLIP

- 260.1.59 MOTHER FRAME
- 265.1.42 GEAR BOX
- 602.1.23 SCREW (4 OFF)
- 602.1.26 SCREW

- 232.1.14 WASHER(2 OFF)
- 600.1.85 - SCREW(2 OFF)
- 500.1.32 TRIGGER
- 600.1.63 SCREW
- 329.1.25 HANDLE(TOP)
- 329.1.26 HANDLE(BOTTOM)
- 360.1.52 SLEEVE

- 278.1.53 CLAMP
- 600.1.82(2 OFF) SCREW
- 600.1.29 SCREW
- 606.1.24 WASHER
- 500.1.43 SWITCH INSULATION
- 330.1.08 SWITCH

- 601.1.28 SCREW(2 OFF)
- 231.1.14 WASHER(2 OFF)
- 604.1.16 NUT (2 OFF)
- 500.1.35 LINK PIN
- 311.1.85 RETAINING RING
- 310.1.63 SPRING

- SCREWS 600.1.77

- 500.1.33 PIN(2 OFF)
- 500.1.34 LINK
- 312.1.12 BEARING COVER (2 OFF)
- 275.1.92 KEY
- 300.1.63 GEAR
- 300.1.64 GEAR
- 300.1.65 GEAR
- 275.1.92 KEY
- 300.1.80 GEAR
- 300.1.83 GEAR
- 230.1.25 WASHER
- 274.1.44 BEARING(4 OFF)
- 300.1.84 GEAR

FW 805.1.33 FITTED ON ASSEMBLY OFF FRAME & BRUSH HOLDER SUPPORT TO BE A GOOD FIT IN FRAME

### ITEMS NOT SHOWN

- 337.1.61 DRIFT
- 800.1.33 PIN(2 OFF)
- 800.1.42 PLUG(2 OFF)
- 403.3.62 CABLE ASBY

- 310.1.36 SPRING
- 600.1.37 PLUNGER
- 600.1.38 PLUNGER CAP
- 500.1.31 BREAST PLATE
- 606.1.23 WASHER(2 OFF)
- 600.1.03 SCREW(2 OFF)
- 254.1.16 ROCKER(2 OFF)
- 601.1.28 SCREW(4 OFF)

NOTE :

1. BEARING (272.1.54) MUST BE ASSEMBLED AS FOLLOWS INNER WASHER WITH SLIGHTLY LARGER BORE TO BE PRESS FIT IN GEAR BOX END CLEARANCE ON DRILL SPINDLE
2. PART NO. 6 WRITTEN IN THE BOX ARE ONLY FOR NW 10 AR

FOR SPARE CARBON BRUSH SET - 251.9.29