
Professional Rotary Hammer

Ralli Wolf



MODEL NO.93400





Turn the arrow to the picture show position, then machine perform strike&drill function



Turn the arrow to the picture show position, then machine perform strike function



Change the carbon brush



Speed button: 1-6 setting



Grease(40-50g)



Press down the collet chuck, insert the bit in then release the collet chuck to lock the bit; to take the bit out, just press down the collet chuck.



